



Dart Aerospace Ltd.
1270 Aberdeen St
Hawkesbury, ON
K6A 1K7
Canada

Tel (613) 632-5200
Fax 613 632-5246

648.4707

Job Sheet 186778



Part No: 648.4707

Job Qty: 1 ea

Part Name: SWA3 Overhaul Provisions



Part Weight: 0 lbs

Status: New

Priority: Medium

Job Created: 11/21/18

Job Tracking No:

Due Date: 12/10/18

Created By: Marie Lajeunesse

Type: SOLD

Description:

Note: O&OPM-SWA3 REV.3 IPP REV:A 17.12.12 NEW ISSUE DD VERF:JFS

Ship Via:

Bill of Materials

Job Routing

Op No	Operation	Qty	Start Date	Due Date	Standard		Workcenter/Supplier		Sign-off
					Setup Hrs	Run Hrs	Workcenter / Supplier	Lead Time	
90	Start up Operation	1 Ea	12/10/18	12/10/18	0.00	0.00	Start Up Stores/Pkg-1		
110	Small Fab	1 pcs	12/10/18	12/10/18	0.00	0.00	Small Fab-3		
120	QC	1 pcs	12/10/18	12/10/18	0.00	0.00	QC4	DEC 12 2018	DAS 46
130	Packaging	1 pcs	12/10/18	12/10/18	0.00	0.00	Packaging3-1	DEC 12 2018	46 9-89
135	DC	1 pcs	12/10/18	12/10/18	0.00	0.00	DC		DAS 9-89
140	QC21-FG	1 Ea	12/10/18	12/10/18	0.00	0.00	QC21		DAS 9-89

Part Op 110 - Pack, bag and label
Descriptions: 130 - Identify and pack for shipping as per PPP 648.4707
135 - Photocopy bluefile & type labels per PPP 648.4707

Job BOM

Part / Item	Component Name	Quantity	Operation	Container
188-FPSS-832-1/4	Set Screw	1 Ea (1 ea)	90-Start up Operation	5027241
188-FPSS-832-3/8	Set Screw	1 Ea (1 ea)	90-Start up Operation	5027242
188-FSCS-1032-5/8	Set Screw	4 Ea (4 ea)	90-Start up Operation	5047611
600.1319	Up Decal	1 Ea (1 ea)	90-Start up Operation	5037066
EL314-SJTOW	Long Line Electrical Wire, 14/3 Gauge	6 ft (6 ea)	90-Start up Operation	5047707
SWA3-400	Button Head Screw	2 Ea (2 ea)	90-Start up Operation	5133901
SWA3-600	O-Ring	1 Ea (1 ea)	90-Start up Operation	5119053
SWA3-700	9529K15 Bearing Balls - 1/4"	32 Ea (32 ea)	90-Start up Operation	5097699
SWA6A-1900	1/4" Female Spade Connector	6 Ea (6 ea)	90-Start up Operation	5084069
SWA6A-2000	1/8" Female Spade Connector	4 Ea (4 ea)	90-Start up Operation	5097727

Job Allocations

Operation	Component Part	Required	Inventory	Allocated
90-Start up Operation	188-FPSS-832-1/4	1	41	0
	188-FPSS-832-3/8	1	51	0
	188-FSCS-1032-5/8	4	241	0
	600.1319	1	212	0
	EL314-SJTOW	6	432	0
	SWA3-400	2	14	0
	SWA3-600	1	18	0
	SWA3-700	32	368	0
	SWA6A-1900	6	507	0

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation			Disposition		
			Completed By		
			Lead hand / Supervisor Approval Verification		
			QC / QA Coordinator Approval		
Root Cause		FAULT CATEGORY			
Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐	No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐	Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐	Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐	Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐	Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐
OTHER :					

Part Specifications

Specifications could not be found.

Plex 11/21/18 10:26 AM Dart.lajeunesse.marie

DART
AEROSPACE1270 Aberdeen Street
Hawkesbury, ON K6A 1K7
CANADA
TEL.: 1 613 632-5200
Email: sales@dartaero.com
www.dartaerospace.com**Container No: S135968****Part: 648.4707****Job No: 186778****Serial No/Batch: S135968**

Revision: 3

Inspector:

Exp Date:

Instructions:

Date: 12/10/18

DQA: _____ Date: _____



WORK ORDER NON-CONFORMANCE / UPDATE

QA Closed: _____ Date: _____

Work Order update only ☐

Work Order: _____ Part No. _____ NCR No. _____	DISPOSITION Rework ☐ Scrap ☐ Use-as-is ☐ Suspected Unapproved ☐	AGAINST DEPARTMENT/PROCESS Skid-tube ☐ Machining ☐ Thermoforming ☐ Large Fab ☐ Cross tube ☐ Small Fab ☐ Finishing ☐ Composite ☐ Water Jet ☐ Prod. Eng. Coord. ☐ Rec/Store/Packaging ☐ Supplier ☐ Engineering ☐ Quality ☐ Other ☐			
Date :	Step #:	QTY Effective :		MRB (QSI042) Approval	
Description Work Order Deviation		Disposition		Completed By	
				Lead hand / Supervisor Approval Verification	
				QC / QA Coordinator Approval	
Root Cause Environment ☐ Design ☐ Doc/Data ☐ Equip/Tooling ☐ Handling/Pre ☐ Material ☐ Internal Transport ☐ Tribal Knowledge ☐ LOA ☐ Substation ☐ Past Expiry Date ☐ Misidentified ☐ No Re-verification ☐ Operator ☐ Offset/Setup ☐ Supplier ☐ Training ☐ Use for Testing ☐ Poor Information ☐ Rushing ☐ Product Improvement ☐ Process Improvement ☐ Manufacturing Process ☐ Past Due ☐		FAULT CATEGORY Pressure/Forced ☐ Bending ☐ Centre Not Concentric ☐ Cracks ☐ Crimp/Kink/Ripple/Wave ☐ Cuffs ☐ Crushing ☐ Heat Treat ☐ Wave/Twist in Tube ☐ Marks/Chatter ☐ Temperature/Cure ☐ Set-up ☐ BOM/Route ☐ Broken/Damage/Defect ☐ Inspection Incomplete/Unqualified ☐ Contamination ☐ Countersink ☐ Cut Too Short ☐ Instructions Incomplete/Unclear ☐ Drill Holes ☐ Power Loss/Surge ☐ Folio/Program ☐ Grain ☐ Weld ☐ Wrong Stock Pulled ☐ Out of Sequence ☐ Off-set ☐ Misabeled ☐ Fit/Function ☐ Misaligned/off center ☐ Positioned Wrong ☐ Outside Dimensions ☐ Over/Under tolerance ☐ Part Incorrect ☐ Part Lost/Missing ☐ Part Moved ☐ Drawing ☐ Finish ☐ Misread ☐ Turning Sequence ☐			
OTHER : _____					